

<div>✖</div>	Equipment :	Boring Machine	Loss Type :	Defect Loss							KAIZEN IDEA SHEET													
	Department	QA	Result :	N	P	Q	C	D	S	M														
			Type :																					
Cell : KTM Powder coating			Operation : Head pipe ID 52.00 & 48.00 boring.																					
Kaizen Theme: To eliminate rejection in KTM frame (KT04) due to boring operation shift. (uneven wall thickness)			Idea : ROBO welding overlap position away from boring fixture resting area.																					
Problem / Present Status			Counter Measure				Benchmark :		9															
When = Continuous. Who = Boring operation operator. What = boring operation shift. (uneven wall thickness). Where = KTM frame (KT04) boring. Which			End point of ROBO welding shifted away from boring fixture resting area.				Target :		0															
							Start :		18/07/2014															
							Finished :		21/07/2014															
							Note :																	
<p>Gap between head pipe OD & resting pad due to excess weld bead near boring fixture resting area.</p>			<p>No Gap between head pipe OD & resting pad.</p> <p>ROBO welding overlap position away from boring fixture resting area</p>				Team Members : 1. Mr. S K Parhad 2. Mr. Aashis Sawant 3. Mr. Anna Surve 4. Mr. Vinod Theng 5. 6.																	
							Benefits P Inspection operation for frame resting eliminated. Nos 1.00 Q Rejection due to boring operation shift is zero. Nos 0.00 C Rework for excess weld bead is zero. Nos 0.00																	
Why Why Analysis :			Result :				Kaizen Sustenance :																	
W1 : Why Boring operation shift. (uneven wall thickness). ? A1 : Head pipe position shift in upward direction on boring fixture. W2 : Why Head pipe position shift in upward direction on boring fixture. ? A2 : Frame not rest on head pipe OD. W3 : Why Frame not rest on head pipe OD. ? A3 : Excess weld bead near resting area of head pipe OD. W4 : Why Excess weld bead near resting area of head pipe OD. ? A4 : ROBO welding overlap position near resting area.			Rejection due to boring operation shift is zero. <p>Boring operation shift rejection trend</p> <table border="1"> <thead> <tr> <th>Month</th> <th>No's</th> </tr> </thead> <tbody> <tr> <td>Jun-14</td> <td>5</td> </tr> <tr> <td>Jul-14</td> <td>4</td> </tr> <tr> <td>Aug-14</td> <td>0</td> </tr> </tbody> </table>				Month	No's	Jun-14	5	Jul-14	4	Aug-14	0	What To Do : Irreversible kiazen. How To Do : Irreversible kiazen. Frequency : Cost Incurred For Making Kaizen : <table border="1"> <thead> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </tbody> </table>				Material Cost	Labour Cost	Total	0.00	0.00	0.00
Month	No's																							
Jun-14	5																							
Jul-14	4																							
Aug-14	0																							
Material Cost	Labour Cost	Total																						
0.00	0.00	0.00																						
Root Cause ROBO welding overlap position near resting area.							Scope & Plan For Horizontal Deployment : <table border="1"> <thead> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> </thead> <tbody> <tr> <td>Welding machine</td> <td>21/07/2014</td> <td>COMPLETE</td> </tr> </tbody> </table>				Equipmnet	Target	Status	Welding machine	21/07/2014	COMPLETE								
Equipmnet	Target	Status																						
Welding machine	21/07/2014	COMPLETE																						
Date : 18/08/2014 Registered By : Mr. D K Thorve Manager's Sign : Mr Shivakumar																								