S DA IA I	Equipment :	f-40		Loss	Loss Type : Defect Lo									KAIZEN IDEA SHEET				
BAJAJ Dohineliy Aked	Department :	QA		Resu	lt :	N	F	> Q	С	Т	D S		М	1				
	Cell :	C101 FRAME		Туре	:									Kaizen ID : 3108				
Jnit Name : 1001	21 - LUMAX AUTO	urangabad		Opera	tion : Robotic welding													
Kaizen Theme: To el Sea	iminate defect pheno t cowl fitment not pos	omena ssible on C101 frame	Id	ea :	Locati	on clan	npir	ig not on	bolt									
•			Counter Measure						Benchmark : 16									
defect phenomena Seat cowl fitment not possible on C101 frame			Block location shift from bolt Bolt to Guide Block :				Target : 0											
								Start :			5/01/2017			Finished : 25/01/2017		/2017		
								Note : ok										
		r h	_					Team Members :										
								1. ashish						2. dinesh				
								3. kishor patil						4. mahajan				
								5.						6.				
								Benefits										
		Action and Giorging in Bill of - Difficult to retighten - Possibility of Twist						Q Q Saet cowl fitment defect eliminated C cost of poor quality reduced M Moral Increase Rs 20000.00										
Why Why Analysis :			Result :						Kaizen Sustenance :									
V1 : Why Seat cowl fitme	ent not possible on C	C101 frame	Seat Cow fitment not possible						What To Do: check Seat cowl fitment									
1 : Seat cowl bracket sh	ift in X axis																	
V2 : Why Seat cowl brac	ket shift in X axis								How To Do : audit kaizen									
? .2 : Seat cowl locating blo	ock shift in X axis																	
V3 : Why Seat cowl locati		kis	18 16 14 14 12 10 8 6															
2	0								Frequency : WEEKLY									
3 : Locating block loose	10000								Cost Incurred For Making Kaizen :									
N4 : Why Locating block loose ? A4 : Location and Clamping on Bolt Bolt - Difficult to retighten - Possibility of Twist								Material Cost			Labour Cost		Total					
			Dec-16 Jan-17 Feb-17					0.04	4			0.	0.02 0.06					
								Scope & Plan For Horizontal Deploy					Deployn	yment :				
loot Cause			•					Equipmnet							Target	Status		
ocation and Clamping or Bolt - Difficult to retighten	n Bolt - Possibility of Twist	:						ROBOTIC WELDING						07/09/2017 PENDING				
Date : 03/01	1/2017																	
egistered By : Mr. S	Sachin Lahe																	
/anager's Sign: Mr. ⊦			·					1										
Bajaj Auto Ltd.	(Fabrication)																	