



	Equipment :	Welding machine	Loss Type :	Setup & adjustment Loss							KAIZEN IDEA SHEET Kaizen ID : 3161
	Department :	Press & Fab	Result :	N	P	Q	C	D	S	M	
	Cell :	Welding cell at starways waluj	Type :								
Unit Name : Press and Fab - Quality, Pune			Operation : Welding operation								
Kaizen Theme: To eliminate defect of stack height variation (oversize / undersize) in welding m/c			Idea : To control stack height during welding operation								
Problem / Present Status			Counter Measure			Benchmark :		Zero defect generation			
Gear shifting hard defect in PV - 1. Stack height 25 -0.25 mm oversize by 0.5~1 mm 2. Stack height 25 -0.25 mm undersize by 0.5~1 mm			To provide control on stack height by stopper .-Stopper bush provided instead of the reed switch controller to control Height Variation in welding .			Target :		Zero Defect of stack height variation			
						Start :	12/06/2017	Finished :	29/09/2017		
Before:- Stack height oversize and undersize			After :- Stack height - control on welding m/c			Note :					
<div> <div>HIGHT O/S</div>  </div> <div> <div>HIGHT U/S</div>  </div>						Team Members : 1. Miss. Priti Sakhare 2. Mr. Gaurikar (M/s S 3. 4. 5. 6.					
Why Why Analysis :			Result :			Kaizen Sustenance :					
W1 : Why Stack height oversize / undersized ? A1 : During welding operation - shaft slightly rest on weld spatter / Shaft rest down in serration block W2 : Why During welding operation - shaft slightly rest on weld spatter / Shaft rest down in serration block ? A2 : During Welding - welding spot stuck in serration ring gauge / Shaft rest down in serration block W3 : Why During Welding - welding spot stuck in serration ring gauge / Shaft rest down in serration block ? A3 : No control of height during welding operation W4 : Why No control of height during welding operation ? A4 :			Stack height variation (undersize / oversize) phenomena rejection reduced to Zero 			What To Do : To confirm stack height 25 -0.2 mm How To Do : 1. Process pokayoke monitoring 2. 100 % inspection by gauge Frequency : Daily Basis					
Root Cause						Cost Incurred For Making Kaizen :					
No control of height during welding operation						Material Cost		Labour Cost		Total	
Date : 29/09/2017						0.00		0.00		0.00	
Registered By : Ms Priti Sakhare						Scope & Plan For Horizontal Deployment :					
Manager's Sign :						Equipmnet		Target		Status	
----- BAL Prass and Fab Team -----											