BAJAJ	Equipment :	Gusset Assly							Loss Type : Defect Los						KAIZEN IDEA SHEET			
> DAJAJ	Department :	Quality						Result :		F	P Q	С	D	S	М	1		
Ustruttly Ahead	Cell:	BM 100/150 Robotic	Туре	:									Kaizen ID : 5	32				
Jnit Name: 1001	urangabad Operati					ation :	F	Rider Step Assly										
Kaizen Theme: To re	educe inhouse defec	t of Rider Step not qualifying	o relation	gauge		Id	ea:	Restir	ng to lov	ver	pipe							
Problem / Present Status			Counter Measure							Benchmark: 17								
Rider Step of BM 100/150 Frame Assly not qualifying to relation gauge			Resting to lower pipe provided on fixture					Target: 0			0							
											Start :		07/01/2	013	1	Finished :	19/04	/2013
			100							т	Note :					•	•	
	100			RIC	ler Step	BKt	7			ı	Team M	lember	s:					
Lower Pipe Rider step bkt									ı	1. Mr. Raosaheb Bansode					2. Mr. Rahul Kumawat			
									ı	3. Mr. Pushkar Vaidya				4. Mr. Mayur Bagate				
									ı	5.				6.				
										Benefits								
No Stopper Provision to Rider Step				LowerPipe						C Cost of poor quality reduced by Rs 0.00								
No Stopper Frovisi	on to Rider Step					- K		-										
					Stoppe			160	100									
Why Why Analysis : W1 : Why Rider Step not qualifying to relation gauge ?				Result: IHR trend -Rider Step of BM 100/150 Frame Assly not qualifying to relation							Kaizen Sustenance : What To Do : No spatter on resting block, No loose, No wear out							
,	. , ,		IHR tre	nd -Rider S	tep of BM 100	0/150 Frame Ass	sly not qu	alifying t	to relati	on	What To	Do : N	lo spatte	r on r	esting blo	ck, No loose,	No wear out	
1 : Rider Step Bkt position		-	3 3															
N2: Why Rider Step Bkt position varies in 'X' & 'Z' direction by 1 to 2 mm?											How To Do : Spatter cleaning , Retighting of block,(JH) Block dimesions inspection (PM)							
A2 : Lower pipe shift in 'Z' direction			25															
V3 : Why Lower pipe shift in 'Z' direction ?			20 - Before After															
A3 : No resting to lower pipe in fixture			15 -							Frequency : JH - Daily, PM -weekly								
N4: Why No resting to lower pipe in fixture?											Cost Incurred For Making Kaizen :							
4:			10 -								М	aterial	Cost		Labo	our Cost	1	Fotal
			5 -		4	2			2			1000.0	00		3(00.00	13	00.00
			0 +			2	1		2		Scope			izont			10	
			Apr-13 May-13 Jun-13 Jul-13 Aug-13							Scope & Plan For Horizontal Deploym Equipmnet					Target Status			
coot Cause No resting to lower pipe in	n fixture												Ече	ірппі	<u> </u>		raiget	Status
Date : 07/01	1/2013		1															
	Sachin Lahe																	
Manager's Sign: Mr. ⊢	lemant Sriwastava																	
Bajaj Auto Ltd.	(Enhrication)																	·