


















	Equipment :	Frame Assembly	Loss Type :	Defect Loss							KAIZEN IDEA SHEET Kaizen ID : 2468																																																																																																																																					
	Department :	Quality	Result :	N	P	Q	C	D	S	M																																																																																																																																						
	Cell :	3wh-line	Type :																																																																																																																																													
Unit Name : 112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj), Aurangabad			Operation : Welding																																																																																																																																													
Kaizen Theme: To eliminate defect Bottom reinforcement damage during bending operation.			Idea : Holding to overhang area																																																																																																																																													
Problem / Present Status			Counter Measure				Benchmark :		103																																																																																																																																							
Bottom reinforcement damage during bending operation			providing support to bottom reinforcement overhang area at rear bottom side.				Target :		0																																																																																																																																							
							Start :		16/06/2014		Finished :		25/06/2014																																																																																																																																			
							Note :																																																																																																																																									
Why Why Analysis : W1 : Why Bottom reinforcement shifted during bending operation ? A1 : Bottom reinforcement unbalance. W2 : Why Bottom reinforcement unbalance ? A2 : Bottom reinforcement overhang area up to 600mm. W3 : Why Bottom reinforcement overhang area up to 600mm. ? A3 : No holding to over hang area. W4 : Why No holding to over hang area. ? A4 :			Result : Reduce In house rework <table border="1"> <tr> <th colspan="2">CAUSE SIDE ACTION</th> <th>Implemented Date :- 25.06.2014</th> </tr> <tr> <td colspan="2">Theme :- To eliminate defect Bottom reinforcement damage during bending operation.</td> <td rowspan="2">Result- In house rework</td> </tr> <tr> <td colspan="2">Problem present status :- Bottom reinforcement damage during bending operation.</td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table> </td> <td colspan="4"> Team Members : 1. K.M.Badgujar 2. K.P.Lagwankar 3. K.G.Narwade 4. K.M.Ghayal 5. 6. </td> <td colspan="2"> Benefits M Moral of operator increase Rs 0.00 </td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Why Why Analysis : W1 : Why Bottom reinforcement shifted during bending operation ? A1 : Bottom reinforcement unbalance. W2 : Why Bottom reinforcement unbalance ? A2 : Bottom reinforcement overhang area up to 600mm. W3 : Why Bottom reinforcement overhang area up to 600mm. ? A3 : No holding to over hang area. W4 : Why No holding to over hang area. ? A4 : </td> <td colspan="4"> Result : Reduce In house rework <table border="1"> <tr> <th colspan="2">CAUSE SIDE ACTION</th> <th>Implemented Date :- 25.06.2014</th> </tr> <tr> <td colspan="2">Theme :- To eliminate defect Bottom reinforcement damage during bending operation.</td> <td rowspan="2">Result- In house rework</td> </tr> <tr> <td colspan="2">Problem present status :- Bottom reinforcement damage during bending operation.</td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table> </td> <td colspan="4"> Kaizen Sustenance : What To Do : Point to be added check sheet How To Do : Maintain JH check sheet daily basis Frequency : Daily </td> <td colspan="2"> Cost Incurred For Making Kaizen : <table border="1"> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </table> </td> <td colspan="2"> Scope & Plan For Horizontal Deployment : <table border="1"> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> <tr> <td colspan="3"></td> </tr> </table> </td> </tr> <tr> <td colspan="3"> Root Cause No holding to over hang area. </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Date : 22/12/2014 </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Registered By : Mr. A S Pawar </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Manager's Sign : Mr. D T RANE </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="11">----- Bajaj Auto Ltd. (Fabrication) -----</td> </tr> </table> </td></tr></table>				CAUSE SIDE ACTION		Implemented Date :- 25.06.2014	Theme :- To eliminate defect Bottom reinforcement damage during bending operation.		Result- In house rework	Problem present status :- Bottom reinforcement damage during bending operation.		<table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table>		Before	After	Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.	<table border="1"> <tr> <td></td> <td></td> </tr> </table>					Root Cause :- No holding to over hang area Horizontal Deployment :- No				Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.	Team Members : 1. K.M.Badgujar 2. K.P.Lagwankar 3. K.G.Narwade 4. K.M.Ghayal 5. 6.				Benefits M Moral of operator increase Rs 0.00				Why Why Analysis : W1 : Why Bottom reinforcement shifted during bending operation ? A1 : Bottom reinforcement unbalance. W2 : Why Bottom reinforcement unbalance ? A2 : Bottom reinforcement overhang area up to 600mm. W3 : Why Bottom reinforcement overhang area up to 600mm. ? A3 : No holding to over hang area. W4 : Why No holding to over hang area. ? A4 :			Result : Reduce In house rework <table border="1"> <tr> <th colspan="2">CAUSE SIDE ACTION</th> <th>Implemented Date :- 25.06.2014</th> </tr> <tr> <td colspan="2">Theme :- To eliminate defect Bottom reinforcement damage during bending operation.</td> <td rowspan="2">Result- In house rework</td> </tr> <tr> <td colspan="2">Problem present status :- Bottom reinforcement damage during bending operation.</td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table> </td> <td colspan="4"> Kaizen Sustenance : What To Do : Point to be added check sheet How To Do : Maintain JH check sheet daily basis Frequency : Daily </td> <td colspan="2"> Cost Incurred For Making Kaizen : <table border="1"> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </table> </td> <td colspan="2"> Scope & Plan For Horizontal Deployment : <table border="1"> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> <tr> <td colspan="3"></td> </tr> </table> </td> </tr> <tr> <td colspan="3"> Root Cause No holding to over hang area. </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Date : 22/12/2014 </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Registered By : Mr. A S Pawar </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Manager's Sign : Mr. D T RANE </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="11">----- Bajaj Auto Ltd. (Fabrication) -----</td> </tr> </table>				CAUSE SIDE ACTION		Implemented Date :- 25.06.2014	Theme :- To eliminate defect Bottom reinforcement damage during bending operation.		Result- In house rework	Problem present status :- Bottom reinforcement damage during bending operation.		<table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table>		Before	After	Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.	<table border="1"> <tr> <td></td> <td></td> </tr> </table>					Root Cause :- No holding to over hang area Horizontal Deployment :- No				Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.	Kaizen Sustenance : What To Do : Point to be added check sheet How To Do : Maintain JH check sheet daily basis Frequency : Daily				Cost Incurred For Making Kaizen : <table border="1"> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </table>		Material Cost	Labour Cost	Total	0.00	0.00	0.00	Scope & Plan For Horizontal Deployment : <table border="1"> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> <tr> <td colspan="3"></td> </tr> </table>		Equipmnet	Target	Status				Root Cause No holding to over hang area.											Date : 22/12/2014											Registered By : Mr. A S Pawar											Manager's Sign : Mr. D T RANE											----- Bajaj Auto Ltd. (Fabrication) -----										
							CAUSE SIDE ACTION		Implemented Date :- 25.06.2014																																																																																																																																							
							Theme :- To eliminate defect Bottom reinforcement damage during bending operation.		Result- In house rework																																																																																																																																							
Problem present status :- Bottom reinforcement damage during bending operation.																																																																																																																																																
<table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table>		Before	After	Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.	<table border="1"> <tr> <td></td> <td></td> </tr> </table>					Root Cause :- No holding to over hang area Horizontal Deployment :- No				Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.	Team Members : 1. K.M.Badgujar 2. K.P.Lagwankar 3. K.G.Narwade 4. K.M.Ghayal 5. 6.				Benefits M Moral of operator increase Rs 0.00																																																																																																																												
Before	After																																																																																																																																															
Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.																																																																																																																																															
<table border="1"> <tr> <td></td> <td></td> </tr> </table>																																																																																																																																																
Root Cause :- No holding to over hang area Horizontal Deployment :- No																																																																																																																																																
		Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.																																																																																																																																														
Why Why Analysis : W1 : Why Bottom reinforcement shifted during bending operation ? A1 : Bottom reinforcement unbalance. W2 : Why Bottom reinforcement unbalance ? A2 : Bottom reinforcement overhang area up to 600mm. W3 : Why Bottom reinforcement overhang area up to 600mm. ? A3 : No holding to over hang area. W4 : Why No holding to over hang area. ? A4 :			Result : Reduce In house rework <table border="1"> <tr> <th colspan="2">CAUSE SIDE ACTION</th> <th>Implemented Date :- 25.06.2014</th> </tr> <tr> <td colspan="2">Theme :- To eliminate defect Bottom reinforcement damage during bending operation.</td> <td rowspan="2">Result- In house rework</td> </tr> <tr> <td colspan="2">Problem present status :- Bottom reinforcement damage during bending operation.</td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table> </td> <td colspan="4"> Kaizen Sustenance : What To Do : Point to be added check sheet How To Do : Maintain JH check sheet daily basis Frequency : Daily </td> <td colspan="2"> Cost Incurred For Making Kaizen : <table border="1"> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </table> </td> <td colspan="2"> Scope & Plan For Horizontal Deployment : <table border="1"> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> <tr> <td colspan="3"></td> </tr> </table> </td> </tr> <tr> <td colspan="3"> Root Cause No holding to over hang area. </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Date : 22/12/2014 </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Registered By : Mr. A S Pawar </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="3"> Manager's Sign : Mr. D T RANE </td> <td colspan="4"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> <tr> <td colspan="11">----- Bajaj Auto Ltd. (Fabrication) -----</td> </tr> </table>				CAUSE SIDE ACTION		Implemented Date :- 25.06.2014	Theme :- To eliminate defect Bottom reinforcement damage during bending operation.		Result- In house rework	Problem present status :- Bottom reinforcement damage during bending operation.		<table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table>		Before	After	Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.	<table border="1"> <tr> <td></td> <td></td> </tr> </table>					Root Cause :- No holding to over hang area Horizontal Deployment :- No				Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.	Kaizen Sustenance : What To Do : Point to be added check sheet How To Do : Maintain JH check sheet daily basis Frequency : Daily				Cost Incurred For Making Kaizen : <table border="1"> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </table>		Material Cost	Labour Cost	Total	0.00	0.00	0.00	Scope & Plan For Horizontal Deployment : <table border="1"> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> <tr> <td colspan="3"></td> </tr> </table>		Equipmnet	Target	Status				Root Cause No holding to over hang area.											Date : 22/12/2014											Registered By : Mr. A S Pawar											Manager's Sign : Mr. D T RANE											----- Bajaj Auto Ltd. (Fabrication) -----																																																	
CAUSE SIDE ACTION		Implemented Date :- 25.06.2014																																																																																																																																														
Theme :- To eliminate defect Bottom reinforcement damage during bending operation.		Result- In house rework																																																																																																																																														
Problem present status :- Bottom reinforcement damage during bending operation.																																																																																																																																																
<table border="1"> <tr> <th>Before</th> <th>After</th> </tr> <tr> <td> Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area. </td> <td> Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side. </td> </tr> <tr> <td colspan="2"> <table border="1"> <tr> <td></td> <td></td> </tr> </table> </td> <td rowspan="2">  </td> </tr> <tr> <td colspan="2"> Root Cause :- No holding to over hang area Horizontal Deployment :- No </td> </tr> <tr> <td colspan="2"></td> <td> Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet. </td> </tr> </table>		Before	After	Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.	<table border="1"> <tr> <td></td> <td></td> </tr> </table>					Root Cause :- No holding to over hang area Horizontal Deployment :- No				Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.	Kaizen Sustenance : What To Do : Point to be added check sheet How To Do : Maintain JH check sheet daily basis Frequency : Daily				Cost Incurred For Making Kaizen : <table border="1"> <tr> <th>Material Cost</th> <th>Labour Cost</th> <th>Total</th> </tr> <tr> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> </table>		Material Cost	Labour Cost	Total	0.00	0.00	0.00	Scope & Plan For Horizontal Deployment : <table border="1"> <tr> <th>Equipmnet</th> <th>Target</th> <th>Status</th> </tr> <tr> <td colspan="3"></td> </tr> </table>		Equipmnet	Target	Status																																																																																																																
Before	After																																																																																																																																															
Analysis :- W1 : Bottom reinforcement shifted during bending operation. W2 : Bottom reinforcement unbalance. W3 : Bottom reinforcement overhang area upto 600mm. W4 : No holding to over hang area.	Kaizen Idea:- Holding to overhang area Counter Measure:- providing support to bottom reinforcement overhang area at rear bottom side.																																																																																																																																															
<table border="1"> <tr> <td></td> <td></td> </tr> </table>																																																																																																																																																
Root Cause :- No holding to over hang area Horizontal Deployment :- No																																																																																																																																																
		Benefit:- Reduce in house rejection and rework Sustenance :- Point is added in daily JH check sheet.																																																																																																																																														
Material Cost	Labour Cost	Total																																																																																																																																														
0.00	0.00	0.00																																																																																																																																														
Equipmnet	Target	Status																																																																																																																																														
Root Cause No holding to over hang area.																																																																																																																																																
Date : 22/12/2014																																																																																																																																																
Registered By : Mr. A S Pawar																																																																																																																																																
Manager's Sign : Mr. D T RANE																																																																																																																																																
----- Bajaj Auto Ltd. (Fabrication) -----																																																																																																																																																