S DA IA I	Equipment :	Fixture	L	Loss Type :	Defect	Los	ss						KAIZEN IDEA SHEET					
<b>S</b> BAJAJ	Department :	Fabrication		Ī	Result :		Р	Q	С	D	S	N	М					
Distinctly Ahead	Cell:	Swing Arm assembly K2/k	(3	7	Туре :									Kaizen ID : 2492				
Unit Name: 1055	•	Operation: Welding																
Kaizen Theme: To eli	iminate customer/ in-h	ouse complaint due to part n	nissing.	n to	o be provided.													
Problem / Present Status			Counter Measure					Benchmark: 03 Nos.				los.						
K3 Swing Arm Chain slider location bracket missing			Limit switch provided to detect Bracket at M10 tapping stage and interlowith tapping machine. Cycle should not start if bracket missing.			interloc	ked	Target :				0						
								Start : 09/08/2014		2014	Finished :		11/08/2	014				
									Note :									
							Team Members :											
							1. Mr. Pramod Jadhav			2. Mr. M	2. Mr. Milind Limaye							
									3. Mr. Sahebrao Pawar				4. Mr. Y	4. Mr. Yogesh Kota				
							5.				6.	6.						
								Benefits										
00		00	Limit switch is provided to check				Q Possibility of part missing eliminated Rs 0.00											
presence	ision to check the ce of Chain slide cating Bkt.		the presence of Z-	Bkt.	العد الما													
Why Why Analysis :			Result:						Kaizen Sustenance :									
W1 : Why K3 Swing Arm Chain slider location bracket missing ?			Zero customer/ in-house complaints of part missing.						What To Do : Kaizen sustenance/ Pokayoke audit									
A1 : Operator forgot to load bracket																		
W2 : Why Operator forgot to load bracket ?									How To Do : Checking defective sample job on tapping machine. Cycle should not start with defective sample job.									
A2 : Operator negligence (Human error)																		
W3 : Why Operator negligence (Human error) ?			3.50 3.00 2.50															
A3 : No provision of auto detection								Frequency: Daily										
W4 : Why No provision of a	auto detection ?		2.00 -					Cost Ir	cost Incurred For Making Kaizen :									
A4 :			1.50 -					Material Cost			Labour Cost			Total				
			0.50					950.0	00			0.00	00 950.00					
			0.00		0.00			Scope & Plan For Horizontal Deployment :										
Root Cause			Before		After	Equipmnet					Target Status							
No provision of auto detec	tion																	
Date : 12/12	2/2014																	
	alim Shaikh																	
Manager's Sign: Mr. M																		
Bajaj Auto Ltd.			•					-										