W2: Why shift in position of bracket ? A2: location is not arrested properly W3: Why location is and arrested properly Y3: Location is arrested only with single pin W4: Why Location is arrested only with single pin A4: Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016	S PA IA I	Equipment :	Fixture				oss Type :	Defect	t Los	S					ľ	KAIZEN IDEA SHEET					
Link Hame: Diges: Katzen ID: 2899 Katzen Theme: To 284-F RUCHAL EKSINEERINK POR LUTD., Aurangabad Operation : Weight in the selection in t		Department :	Production				esult :	N	F	> Q	С	D	S	Ν	М						
Kaizen Theme: To reduce in house rejection due to Welding Shift Idea : Change in design of block for proper location Problem / Present Status Counter Measure Benchmark : 9 Engine mounting support bracket shift & welding shift Adequate location with 2 pins & supporting plate provided in fixture for preer location Finaleed : 1307/2016 With the intervention Finaleed : 1307/2016 State :: Image: Counter Measure With Wry Analysis : Result : Result : Counter Measure due to Value of the counter with 2 pins & supporting plate provided in future for proef location 2 Sea :: 0 Sea :	Ustinetly Ahead	Cell :	Robotic line A	т	ype :									Kaiz	aizen ID : 2889						
Problem / Present Status Counter Measure Benchmark : 9 Engine mounting support bracket shift & welding shift Adequate location with 2 pins & supporting plate provided in future for proper location Target : 0 Start : 0507/2016 Finished : 1307/2016 Wit Why Analysis : Result : 0 Start : 0 Wit Why Engine mounting support bracket welding shift ? A. 4. Start : 0 A1 : shift in position of bracket ? Result ? Note Start : 0 Start : 0 Wit Why Chardnei is not arrested property Result ? Note Start : Note Start :	Unit Name : 10026	64 - RUCHA ENGINEE	RING PVT LTD., Aurangaba	d Operation : Welding																	
Engine mounting support bracket shift & welding shift Adequate location with 2 pins & supporting plate provided in fixture for priper tocation Target : 0 Start : 05/07/2016 Finished : 13/07/2016 Why Why Analysis : Target :: 0 WH Why Analysis : Result : 1.8G Dabhade 2.8P Sankate Mine : 3.8R Markad 4. - So : 0. 8.8 8.8 WH Why Analysis : Result : Not :: - W1 Why Casion of bracket welding shift ? In-house Rejection Reduced to Zero Kaizen Sustenance : - W1 Why Location is not arrested property Throuse Rejection Reduced to Zero What To Do: Fixture PM check sheet. - W1 W1 Wy Location is arrested property Target : - - - W1 W1 Wy Location is arrested property - - - - W1 W1 Wy Location is arrested property - - - - W1 W1 Wy Location is arrested property - - - - - W1 W1 W1 Cock with single pin - - - - - At : Design of b	Kaizen Theme: To reduce in house rejection due to Welding Shift Idea : Change in design of block for prop												ation								
Image:	Problem / Present Status				Counter Measure						Benchmark : 9										
Star: 05/07/2016 Finished: 13/07/2016 Wote:	Engine mounting support bracket shift & welding shift									Target : 0											
Why Why Analysis : Result : 1. SG Dabhade 2. SP Sarkate 3. BR Markad 4. -				proper location					Start : 05/07/2016				Fini	Finished : 13/07/2016							
Why Why Analysis : Result : I. SG Dabhade 2. SP Sarkate Why Why Charlowsis : Result : Benofits I. HR REDUCED TO ZERO Nos 0.00 Why Why Engine mounting support bracket welding shift ? In-house Rejection Reduced to Zero Kaizen Sustenance : What To Do : Fisture PM W1 : Why Location is not arrested properly ? W2 : Why shift is goalin of bracket ? ? W2 : Why shift is not arrested properly ? Y. Why this ingle pin W4 : Why Location is arrested ony with single pin W4 : Why Location is and arrested ony with single pin W2 : Why shift cost A : Design of block with single pin Design of block with single pin Design o								1	Note :	Note :						-					
Wy Why Analysis: Result: 3. BR Markad 4. S. Benefits - Q Infit ReDUCED TO ZERO Nos 0.00 - Why Why Analysis: Result: - M1: Why Engine mounting support bracket weiding shift ? In-house Rejection Reduced to Zero - M2: Why shift in position of bracket ? Result: - - M3: Why location is not arrested properly - - - M3: Why location is arrested only with single pin - - - M4: Why Location is arrested only with single pin - - - M4: Why Location is arrested only with single pin - - - M4: Why Location is arrested only with single pin - - - M4: Design of block with single pin - - - - Root Cause - - - - - Design of block with single pin - - - - - Date : 05/07/2016 - - - - - Date : 05/07/2016 - - - -<			Contraction of the second seco							Team Members :											
Why Why Analysis : 6. With Why Analysis : 0 W1 : Why Engine mounting support bracket welding shift ? 7. A1 : shift in position of bracket In-house Rejection Reduced to Zero W2 : Why shift in position of bracket ? Result : A2 : clocation is not arrested properly In-house Rejection Reduced to Zero W3 : Why location is not arrested properly What To Do : Point added in fixture PM check sheet . W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero Root Cause In-house Rejection Reduced to Zero In-house Rejection Reduced to Zero Design of block with single pin In-house Rejection Reduced to Zero In-house Rejection Reduced to Zero Data : 0	7									1. SG Dabhade					2. S	2. SP Sarkate					
Benefits Continue Why Why Analysis : Result : W1 : Why Engine mounting support bracket welding shift ? In-house Rejection Reduced to Zero A1 : shift in position of bracket In-house Rejection Reduced to Zero W2 : Why shift in position of bracket ? A2 : location is not arrested properly W3 : Why location is not arrested properly In-house Rejection Reduced to Zero W3 : Why location is not arrested properly In-house Rejection Reduced to Zero W3 : Why Location is and arrested properly In-house Rejection Reduced to Zero W3 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin In-house Rejection Reduced to Zero Root Cause In-Reduced To Labour Cost Total Design of block with single pin In-Reduced To Zero Arrester Equipment Bate : 05/07/2016 OSHOTZO16 In-Reduced To Zero Arrester										3. BR Markad				4.	4.						
Why Why Analysis : Result : Kaizen Sustemance : W1 : Why Engine mounting support bracket welding shift ? In-house Rejection Reduced to Zero What To Do : Fixture PM M1 : shift in position of bracket In-house Rejection Reduced to Zero What To Do : Fixture PM W2 : Why shift in position of bracket ? A2 : location is not arrested properly Material Cost In-house Rejection Reduced to Zero W3 : Why location is arrested only with single pin G G G In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin G G G In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin G G G In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin G G G In-house Rejection Reduced to Zero W4 : Why Location is arrested only with single pin Root Cause G G In-house Rejection Reduced to Zero In-house Rejection Reduced to Zero Root Cause Design of block with single pin Root Cause In-house Rejection Reduced to Zero In-house Rejection Reduced to Zero In-house Rejection Reduced to Zero Date : 05/07/2016 Doto Joo Joo	00	- Alt							-	5.					6.	6.					
Why Why Analysis : Result : Kaizen Sustenance : W1 : Why Engine mounting support bracket welding shift ? In-house Rejection Reduced to Zero What To Do : Fixture PM A1 : shift in position of bracket In-house Rejection Reduced to Zero What To Do : Point added in fixture PM check sheet . W2 : Why shift in position of bracket ? A2 : location is not arrested properly How To Do : Point added in fixture PM check sheet . W3 : Why Location is arrested only with single pin Image: Cost on Cost		and the second second	1155							Benefits											
W1 : Why Engine mounting support bracket welding shift ? A1 : shift in position of bracket ? A2 : location is not arrested properly W3 : Why location is not arrested properly X3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin W4 : Why Location is arrested only with single pin W4 : Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016	A Destanting									Q IHR REDUCED TO ZERO Nos 0.00											
W1 : Why Engine mounting support bracket welding shift ? A1 : shift in position of bracket ? A2 : location is not arrested properly W3 : Why location is not arrested properly X3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016	1110	21-																			
A1 : shift in position of bracket W2 : Why shift in position of bracket ? A2 : location is not arrested properly W3 : Why location is not arrested only with single pin W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin Root Cause Design of block with single pin Dete : 05/07/2016	Why Why Analysis :				Result :						Kaizen Sustenance :										
W2 : Why shift in position of bracket ? A2 : location is not arrested properly W3 : Why location is not arrested properly Y3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin A4 : Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016					In-house Rejection Reduced to Zero						What To Do : Fixture PM										
A2 : location is not arrested properly W3 : Why location is not arrested properly ? A3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016 Date : 05/07/2016	A1 : shift in position of bracket																				
A2 : location is not arrested properly W3 : Why location is not arrested properly ? A3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016	W2 : Why shift in position of bracket ?										How To Do : Point added in fixture PM check sheet .										
? A3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin A4 : Design of block with single pin Become Arrested only with single pin Root Cause Design of block with single pin Become Arrested only with single pin Date : 05/07/2016 05/07/2016	A2 : location is not arrested properly				Result IBR																
A3 : Location is arrested only with single pin W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin Before Affer Aff	W3 : Why location is not arrested properly																				
W4 : Why Location is arrested only with single pin ? A4 : Design of block with single pin Cost Incurred For Making Kaizen : Root Cause Design of block with single pin Isono 0.00 1500.00 Date : 05/07/2016 Cost/07/2016 Cost Incurred For Making Kaizen : Isono										Frequency : Monthly											
A4 : Design of block with single pin Image: Design of block with single pin Root Cause Design of block with single pin Date : 05/07/2016												Cost Incurred For Making Kaizen :									
Root Cause Design of block with single pin 1500.00 0.00 1500.00 Date : 05/07/2016 05/07/2016 COMPLETE	A4 : Design of block with s	single pin		2 -						Material		Cost Labo		Labour Cos	our Cost		Total				
Root Cause Scope & Plan For Horizontal Deployment : Design of block with single pin Target Status Date : 05/07/2016 COMPLETE				I 1					_		1500.	00 (0.00	0.00 1504		0.00				
Design of block with single pin F-30 Fixture on Robotic line B 20/07/2016 COMPLETE Date : 05/07/2016 Object = 100000000000000000000000000000000000										Scope & Plan For Horizontal Deployment :											
Design of block with single pin Design of block with single pin F-30 Fixture on Robotic line B 20/07/2016 Date : 05/07/2016	Root Cause			<u> </u>																	
		e pin								F-30 Fi	xture or	n Roboti	c line E	3		20/	07/2016	COMPLETE			
	Data : 05/07	/2016																			
I Registered By : Mr S R Pardesh																					
Registered By : Mr.S R Pardeshi Manager's Sign : Mr.R S Makasare																					
Bajaj Auto Ltd. (Fabrication)										1											