S BAIAI	Equipment :	F-40		Loss Type :	Defect	Lo	ss					KAIZE	KAIZEN IDEA SHEET				
<b>≫</b> BAJAJ	Department :	ME			Result :	N		P Q	С	D	S	N	1				
Distinctly Ahead	Cell:	Zone-II		Type :								_ к	Kaizen ID : 2960				
Unit Name: 1078	Opera	ation :	٧	Welding													
Kaizen Theme: Avoid Frequent Break Down of Locating pin Idea: To add Pipe Guide Block which will act as Pipe Arrested.																	
Problem / Present Status			Counter Measure					Benchmark: 4									
While Clamping and Declamping Eng. Mtg. Bush Pin Frequently Broken			By adding guide block Pin will come out from Bush easily					Target: 0				0					
								Start : 10/07/2016		1	Finished :	Finished: 17/07/2016					
		AND DESCRIPTION OF THE PERSON NAMED IN COLUMN 1				Note :			<b>I</b>								
		-				Team Members :											
Contract of the second						7	1. Mr.A	nata Do	Ooke			2. Mr.Shaik	2. Mr.Shaikh S.N.				
	E AND W. A					7	4	3. Mr.R	3. Mr.Ram Ambuse			4.	4.				
		Charles					5.				6.						
								Benefits									
The state of the s									C 1) Reduce spare cost of pin Rs 2000.00								
	The							1.12.23.00									
Why Why Analysis :			Result:	1				Kaizen	Suster	ance .							
W1 : Why Avoid Frequent	Break Down of Location	ng pin ?	1) Eliminate Engine mtg pin broken issue					What To Do : JH & PM									
A1 : Frequent Breakage of	f Engine mtg bush loc	ating pin	Reduce Line breakdown     Reduce spare cost of pin														
W2 : Why Frequent Breakage of Engine mtg bush locating pin ?			of reduce spare cost of pin						Haus To Do s Doint added in daily III 9 DM short about								
A2 : Pine Get Stuck in Bush while going Back after decamping			Result —Bear					How I	How To Do : Point added in daily JH & PM check sheet.								
W3 : Why Pine Get Stuck in Bush while going Back after decamping ?			down (Occurance)														
A3 : No arr-ester from Outside for pipe.			20					Freque	Frequency : Daily								
W4 : Why No arr-ester fror	m Outside for pipe. ?		16					Cost Incurred For Making Kaizen :									
A4:			3					Material Cost La			abour Cost	our Cost Total					
			4					0.00		0.00		0.00	0.00				
			0		o			Scope & Plan For Horizontal Deploy				al Depl		l .			
Post Cours			Before After				Equipmnet						Target	Status			
Root Cause No arr-ester from Outside	for pipe.										-			<u> </u>	-		
	/2016																
Registered By: Mr. M Manager's Sign: Mr. P																	
Bajaj Auto Ltd.		·	L														
= 2929 : 1210 =101	<u> </u>																