×	Equipment :	Welding fixture	Los	ss Type :	Quality	у						ΚΔΙΖΙ	KAIZEN IDEA SHEET				
	Department :	Quality		Res	sult :	N	F	Q	Q C		D S		-				
	Cell:	Weld shop kite-5		Тур		.,	l ·	<u> </u>	+ -			M	┥,	aizen ID : 303	31		
Unit Name: Rucha Engineers Pvt Ltd Plant 2, Ahmedabad									Spot welding								
	prove quality of Side s		l _i	lea ·													
-	Tove quality of olde 3	cai iiiici assiy															
Problem / Present Status			Counter Measure					Benchmark: 2									
Piercing operation missing part ship to customer.			Provision made with mechanical Poka yoke Pin addition in fixture to arrest operation missing					Target:									
								Start : 27/04/2017			Finished :	27/04/2	2017				
×			×					Note :									
								Team Members :									
								1. Sunil Prajapati					2. Pushpa Verma				
							3. Shivam rai					4. Kadam Dalit					
								5.					6.				
							Benefits										
								Q Rejection PPM zero. PPM 0.00									
								C Rejection cost zero Rs 1000.00									
Why Why Analysis :			Result : Kaizen Sustenance :														
Why Why Analysis: W1: Why Hole missing in side seal panel assly.?			Result: After implementation poka yoke rejection zero for hole missing.						What To Do: poka yoke sheet updated.								
A1 : without piercing operation parts fit on spot welding fixture.																	
W2 : Why without piercing operation parts fit on spot welding fixture. ?			×						How To Do : Daily poka yoke check before run the line.								
A2 : no detection in spot welding fixture.																	
W3 : Why no detection in spot welding fixture. ?																	
A3 : design issue.								Frequency : PM plan made for live pokayoke									
W4 : Why design issue. ?								Cost In	curred	For Ma	king K	aizen :					
A4 : no poka yoke for detection of hole missing parts.								Material Cost Labour Cost Total						ntal			
									200.0		+			+			
												300.00 500.00					
								Scope & Plan For Horizontal Deployment : Equipmnet Target Status									
Root Cause									Equipmnet Target Sta						Status		
no poka yoke for detection	of hole missing parts.																
Date : 08/05/2017																	
Registered By: Rucha Engineers Pvt Ltd Plant 2																	
Manager's Sign: Mr. S																	
Durcha Craum C	Corporate																