| | le · · | DOG WELDING | . | | 0 111 | | | | | | | T | | | | | | |
|---|--|-------------------|--|--|-----------------|----------|----------|---|--|---|------------------------|-------------------|------------------------------|----------------|------|--|--|--|
| × | Equipment : | CO2 WELDING | | ss Type : | Qualit | ıy | | | | | | KAIZEN IDEA SHEET | | | | | | |
| | Department : | PRODUCTION | | Re | esult : | N | | P Q | С | D | S | М | | | | | | |
| | Cell: | RE60 WELD SHOP | | Ту | rpe : | | | | | | | | | aizen ID : 311 | 0 | | | |
| Unit Name : Ruci | ha Engineers Pvt Ltd Pl | ant 7, Aurangabad | Operation : | | | | | | ROUND WELDING OF PIN CABLE MOUNTING | | | | | | | | | |
| Kaizen Theme: : PARKING LEVER RHD & LHD ASSLY QUALITY ISS THERE WAS CHANCE OF HOLE MISSING OR HOLE | | | | separate locations for pin to hole | | | | | | | | | | | | | | |
| Problem / Present Status | | | Counter Measure | | | | | Benchmark: 20 | | | | 200 NO | 200 NO'S | | | | | |
| : BF -162038 & BF-162011 parking lever as sly pin cable hole not fix location | | | we provides new fixture added because pin cable hole | | | | | Target : | | | 0 | | | | | | | |
| location | | | | | | | | Start | | 03/05/ | 2017 | | Finished : | 17/05/2 | 2017 | | | |
| | 4.50 | | | | | | | Note : | | There | There is no proper loc | | cation for pin hole fitment. | | | | | |
| | | | 4.4 | Sec. | Designation | | | Team | Membe | rs : | | | | | | | | |
| | | | No. | 10.110 | fatures | added | 7 | 1. WA | SIM SH | AIKH | | | 2. VILAS W | AGH | | | | |
| | 9 9 | | (b) (c) | | | | | 3. RAMHARI KHEDKAR | | | 4. | | | | | | | |
| . 9 | | The second second | | | | | | 5. | | | | | 6. | | | | | |
| 00 | The state of the s | | | | | | Benefits | | | | | • | | | | | | |
| 06-3m | | | | | | | | Q 100% problem solve of rejection PPM 0.00 | | | | | | | | | | |
| | MD WELD | | 15-00 | 2000 | The state of | | ١ | | | | | | | | | | | |
| Why Why Analysis : | | | Result: | | | | | | Kaizen Sustenance : | | | | | | | | | |
| W1 : because fixture no location pin cable at moment | | | poka yoke implemented for hole missing as w | poka yoke implemented for hole missing as well hole twist. | | | | | | What To Do : added IPO sheet of parking lever | | | | | | | | |
| A1 : | | | | | | | | | | | | | | | | | | |
| W2 : there are pin cable lower side not proper resting | | | | | | | | How To Do : to update the IPO sheet as well as added in daily poka yoke check | | | | | | | | | | |
| A2 : | | | | | | | ٦ | sheet | | | | | | , | , | | | |
| W3 : in fixture not having | poka yoke pin | | | | laculture p | address. | |) | | | | | | | | | | |
| A3: | | | 70000 | | | | | | Frequency : daily | | | | | | | | | |
| W4 : | | | Carl A | | 1 | | | Cost Incurred For Making Kaizen : | | | | | | | | | | |
| A4 : | | | | | | 1 | | | Materia | Cost | | Labo | our Cost | To | otal | | | |
| | | | | | | 1 | K | | 4000 | .00 | | 6 | 00.00 | 460 | 0.00 | | | |
| | | | | 20000 | To the state of | | | | Scope & Plan For Horizontal Deployment : | | | | | | | | | |
| Root Cause | | | V A LOS | | | | 1 | T. | Equipmnet Target | | | | | Status | | | | |
| | | | | | | | | | | | | | | | | | | |
| | | | _ | | | | | | | | | | | | | | | |
| Date : 08/0 | 9/2017 | | | | | | | | | | | | | | | | | |
| | 9/2017 ha Engineers Pvt Ltd Pla | ant 7 | - | | | | | | | | | | | | | | | |
| | na Engineers Pvt Ltd Pla | ant 7 | | | | | | | | | | | | | | | | |
| Registered By: Ruch | ha Engineers Pvt Ltd Pla S G Sohoni | ant 7 | - | | | | | | | | | | | | | | | |