BAJAJ Dohnely Heal	Equipment :	Tubemillcutter					Defect	Loss	S					KAIZE	KAIZEN IDEA SHEET			
	Department :	Production				Result :	N	Р	Q	С	D	S	М	-				
	Cell :	Tubemill			Type :								Kaizen ID : 2727					
								tuk	tubecutting									
Kaizen Theme: Improvement in Quality & Productivity with reduction in Accident Idea: To make the one stopper for smaller sizes cutting(10mm to 100mm)																		
Problem / Present Status			Counter Measure						Benchmark: 32			3250						
Size variation increases du	e to stopper not availa	We have attached the one bolt to bottom side of the holder & one nut to top					top	Target : 2262				2262						
(55mm,45mm &72.5mm). Quality defect increases as the length variation increases			side of the holder by using welding.					ŀ	Start : 01/03/2		2015)15 Finis		: 13/03/2015				
		x					_	Note :										
						Team Members :												
							Ì	1. Sachin kaluse					2.	2.				
									3. Sachin mahajan				4.					
	12/1					Ì	5.					6.						
									Benefits									
									P production Rs 350.00									
L								C cost saved rejection per month Rs 0.00										
									Q in house rejection Nos 110.00									
Why Why Analysis :								Kaizen Sustenance :										
W1 : Why Length variation		Production increased up-to 3678. with less accident					What To Do : point added in JH/PM sheet											
A1 : Stopper not available t																		
W2 : Why Stopper not available for small sizes(like 72.5,55,45mm) ?									How To Do : check sheet									
A2 : The original stopper not reaches up to the small size																		
W3: Why The original stopper not reaches up to the small size?			3250	3678														
A3:			3250 3000 -					Frequency : Daily										
W4 :		2500 - 2262						Cost Incurred For Making Kaizen :										
A4 :			1500				roduction QTY	QI Y	Material		Cost Labo		our Cost	r Cost Total				
			1000 -							150.0	0			0.00 150.00		50.00		
			0 April May June			July			Scope & Plan For Horizontal Deploy				Deplo	ment :				
Root Cause								Equipmnet						Target	Status			
The original stopper not reaches up to the small size																		
Date : 02/03/	/2015		1															
Registered By: Mr. Ar	mol Girme																	
Manager's Sign: Mr.R	S Makasare																	
Bajaj Auto Ltd. (Fabrication)																	