	Equipment :	L	oss Type :	/ TOOL Lo	oss				KAIZEN IDEA SHEET								
	Department :		F	Result :	N	F	P Q	С	D	S	М	1					
OpExWorks	Cell:			Т	Гуре :								1	Kaizen ID : 279			
Unit Name : Ashwi	ni CAD Systems Pvt. L		I	Opera	ation :	R	Receiving Quality.										
Kaizen Theme: Ejector punch imprecation observed on line of matching area & it leads to leakage. Idea: Ejector punch imprecation observed on line of matching area & it leads to leakage.																	
Problem / Present Status			Counter Measure						Benchmark :								
Ejector punch imprecation observed on line of matching area & it leads to leakage.			Ejector punch imprecation shift with line of matching area.					Target :									
									Start : 10/03/2012		<u> </u>	Finished :	10/03/	2012			
×			×					Note: ok					·				
			Team Members :														
								1.					2.				
								3.					4.				
									5.					6.			
									Benefits								
									C Operating cost reduction Rs 840.00								
Why Why Analysis:			Result:					Kaizen Sustenance :									
W1 : Why Ejector punch imprecation observed on line of matching area. ? A1 : It self position in Die.			Ejector punch imprecation observed out of matching area.						What To Do: Ejector punch imprecation observed on line of matching area & it leads to leakage,So change punch im								
W2 : Why It self position in Die. ?																	
A2 : wrong design.									How To Do: Communicate with supplier related fitment & Punch Position has changed.								
W3 : Why wrong design.			F				onanged.										
A3 : Supplier not aware related fitment.				Frequency: 100%													
W4 : Why Supplier not aware related fitment. ?								Cost Incurred For Making Kaizen :									
A4 :								Material Cost Labor					our Cost	ur Cost Total			
								101			+			+			
							0.00				0.00 0.00						
								Scope & Plan For Horizontal Deployment :									
Root Cause			1					Equipmnet				et		Target	Status		
Supplier not aware related fitment.								3					10/03/2012	COMPLETE			
Date : 10/03/	2012		-														
Registered By : Amit			1														
Manager's Sign: Amit																	
OpExWorks Solu	utions Pvt. Ltd													<u> </u>			