BAJAJ Distinctly Alead	Equipment :	Spot Welding mcahine					Loss Type : Defect Loss								KAIZEN IDEA SHEET		
	Department :	Porduction					N	Р	Q	С	D	S	М				
	Cell:	RE Chassis							Kaizen ID : 2892						aizen ID : 2892		
Unit Name: 100264 - RUCHA ENGINEERING PVT LTD., Aurangabad										Spot welding							
Kaizen Theme: To Re	educe IHR due to Wea	k Spot			Idea	: Provis	sion of F	Poka	ayoke								
Problem / Present Status	3	Counter Measure						Benchmark: 12				12					
IHR due to weak spot			Provided centralize Temperature monitoring Video & Audio System						Target: 0				0				
								Start : 12/07/2016			Finished: 14/07/2016						
***									Note :								
							Team Members :										
							1. RA Lande					2. PM Giram					
	Tel							3. JM Sheikh					4.				
	B							5.					6.				
								Benefits									
								Q IHR due to weak spot reduced to zero Nos 0.00									
Difficult to m																	
Miles Miles Amalesaia	temperature							Weizen Guetananea									
Why Why Analysis : W1 : Why IHR due to weak spot ?			Result : IHR reduced to zero						Kaizen Sustenance : What To Do : Pokayoke audit sheet and Pm sheet								
A1 : voltage variation		III II Toddoca to 2010						How To Do : Monthly Pokayoke audit and PM									
 W2 : Why voltage variation	ı ?																
A2 : transformer overheate																	
W3 : Why transformer ove	rheated?	S 14 12															
A3 : Less water flow / No Water			g 12 8 10						Frequency : monthly								
W4 : Why Less water flow	/ No Water ?	s ion p				Cost Incurred For Making Kaizen :											
A4 : Operator forgot to on water lever			000 000 pasic condition co						Material Cost Labo				Labo	ur Cost Total			
		2			•				0.00								
			00/8			0								.00 0.00			
				Before	After			Scope & Plan For Horizontal Deploy					ment :	Tanada Otatua			
Root Cause								Equipmnet spot welding machine						Target Status 20/07/2016 COMPLETE			
Operator forgot to on wate	r lever							spot weiging machine					ZU/U1/ZU10 COMPLETE				
Date : 12/07	//2016																
Registered By: Mr.S	R Pardeshi																
Manager's Sign: Mr.R																	
Bajaj Auto Ltd.	(Fabrication)																
					· · · · · · · · · · · · · · · · · · ·								<u>-</u>				