



Bajaj Auto Ltd. (Fabrication)

Pune Mumbai Highway, Akurdi,Pune

Pending For Evaluation

Date :23/10/2017

Sr. No	Supplier Name	Kaizen Theme	Registration Date	Implementation Date
1	107851 - AUTOCOMP CORPORATION PANSE PVT LTD	Elimination of Chain case mismatch problem	06/12/2011	10/12/2011
2	108302 - NEEL AUTO PRIVATE LIMITED-Pantnagar	Elimination of customer complaint phenomenon	01/10/2014	04/10/2014
3	107851 - AUTOCOMP CORPORATION PANSE PVT LTD	Elimination of Engine fitment problem due to spatter inside bushes.	10/12/2012	15/12/2012
4	108302 - NEEL AUTO PRIVATE LIMITED-Pantnagar	Implementation of fool proofing on serration marking SPM to avoid wrong side of serration marking	13/09/2013	14/09/2013
5	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	Improvements Of Welding Quality	25/06/2013	01/07/2013
6	112303 - NAHARS ENGINEERING INDIA PVT. LTD	LMPW II-To prevent defect due to Connecting tube cup welding failure	16/11/2013	17/11/2013
7	112303 - NAHARS ENGINEERING INDIA PVT. LTD	LMPW II-To Prevent Scratches on Guard.	15/10/2013	16/10/2013
8	112303 - NAHARS ENGINEERING INDIA PVT. LTD	LMPW II-To reduce IHR for Drain hole Mismatch	12/08/2013	13/08/2013
9	112303 - NAHARS ENGINEERING INDIA PVT. LTD	LMPW II-To reduce IHR for Spatter .	09/10/2013	10/10/2013
10	112303 - NAHARS ENGINEERING INDIA PVT. LTD	Reduce Jig-marks of hanger jigs in front side of Bumper (near hole)	20/05/2014	30/05/2014
11	100211 - UMASONS AUTO COMPO PVT LTD	To prevent IHR due to part wrong part (tube) assembled In BTX swing arm	21/06/2014	21/06/2014
12	111420 - S M AUTO ENGINEERING PVT LTD-Waluj	To Eliminate IHR defect of notch missing brake switch bkt welded.	19/09/2013	19/09/2013
13	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To eliminate rejection for Welding lumps at main member ,lower part & lower reinforcement joining	12/08/2013	17/08/2013
14	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To Eliminate Boring Missing	18/01/2015	27/09/2014
15	107350 - S M AUTO ENGINEERING PVT LTD-Mhalunge	To eliminate CC in KTM JY pipe A assy - Dimple operation missing.	10/10/2013	11/10/2013
16	105139 - KESHARDEEP PRESSINGS	To eliminate CC of G S Cover	07/07/2013	08/07/2013
17	112303 - NAHARS ENGINEERING INDIA PVT. LTD	To eliminate CC of part mismatch	17/09/2013	19/09/2013

18	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To eliminate customer complaint - Air filter fitment not possible	10/06/2013	15/06/2013
19	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	to eliminate customer complaint of air filter difficulty	13/06/2013	25/06/2013
20	105518 - INNOVENTIVE INDUSTRIES LIMITED	To eliminate customer/ in-house complaint due to part missing.	21/05/2015	09/11/2014
21	107851 - AUTOCOMP CORPORATION PANSE PVT LTD	To eliminate defect of Gap Between Swing arm and Pipe LH/RH Joint in avenger frame assly.	21/11/2016	18/08/2016
22	110865 - METALMAN MICRO TURNERS	To Eliminate defect of lower air filter face taper.	30/06/2014	19/03/2014
23	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To eliminate defect phenomena Center stand spring fitment not possible on Platina Frame	10/09/2017	10/09/2017
24	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To Eliminate defect phenomenon of Platina frame Pivot bush comes out from Pivot pipe	30/03/2017	30/03/2017
25	107350 - S M AUTO ENGINEERING PVT LTD-Mhalunge	To eliminate EFR/ Warranty rejection in Disco-m Silencer - Noise due to tail pipe cap loose.	09/01/2013	30/07/2013
26	100428 - BADVE AUTOCOMPS PVT LTD	To eliminate field complaint in silencer due to glass wool wrapping clearance dimensional error	15/01/2013	23/01/2013
27	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To eliminate I.H.R. of welding shift	15/11/2014	25/11/2014
28	111420 - S M AUTO ENGINEERING PVT LTD-Waluj	To Eliminate IHR defect of Air filter Relation not ok.	20/09/2013	25/09/2013
29	100428 - BADVE AUTOCOMPS PVT LTD	To Eliminate IHR of bolt insertion hard in boss due to part position shift	05/09/2013	12/09/2013
30	100428 - BADVE AUTOCOMPS PVT LTD	To eliminate IHR of drain pipe hook missing.	16/11/2013	20/11/2013
31	100428 - BADVE AUTOCOMPS PVT LTD	To Eliminate IHR of Side Stand bkt fitment hard due to spatters in side stand bkt. hole	10/06/2014	22/06/2014
32	108302 - NEEL AUTO PRIVATE LIMITED-Pantnagar	To Eliminate IHR Phenomena of wrong Head Pipe welding.	23/08/2016	23/08/2016
33	100189 - BADVE ENGINEERING LIMITED	To eliminate in house rejection of silencer due to flange hole damage / CD not OK.	20/10/2012	24/10/2012
34	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To eliminate In House rework & customer feedback of full frame assly due to spatter inside driving	21/10/2013	21/10/2013
35	100264 - RUCHA ENGINEERING PVT LTD.	To eliminate In-House Rejection	05/01/2013	08/01/2013
36	100189 - BADVE ENGINEERING LIMITED	To Eliminate Inhouse rejection cost of Body Muffler due to dent at Humping machine. (CT-100 Body Mu	10/11/2013	18/11/2013
37	112933 - Metalman Auto Pvt Ltd.	TO eliminate oozing defect during ACED process in Disco.M swing arm.	25/07/2015	20/04/2015
38	100005 - Shreeganes Press N Coat	To eliminate part missing defect in Mega Passenger seat	17/06/2014	08/05/2014

39	107350 - S M AUTO ENGINEERING PVT LTD-Mhalunge	To eliminate pipe A to pipe B welding bead not uniform in KTM JY exhaust pipe A assembly.	25/06/2013	27/07/2013
40	100428 - BADVE AUTOCOMPS PVT LTD	To eliminate rejection of lock bracket position shift	12/08/2013	16/08/2013
41	100046 - YESHSHREE PRESS COMPS P LTD	To Eliminate Spatter Goes in Side M6 Mudguard strip nut	03/07/2014	25/05/2014
42	110865 - METALMAN MICRO TURNERS	To eliminate the customer complaint (Field failure) - Inner pipe crack in Pipe A assly in silencer B	12/09/2016	12/09/2016
43	110865 - METALMAN MICRO TURNERS	To eliminate the Customer complaint for Mud flap weld nut wrong side welded in Pulsar-150	26/07/2017	27/07/2017
44	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To eliminate the engine bush tapping incomplete issue in frame assembly	15/01/2015	01/09/2014
45	100428 - BADVE AUTOCOMPS PVT LTD	To eliminate warranty for K3 silencer stay hanger & Body B joint.due to weld shift	12/10/2013	05/11/2013
46	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To eliminate wrong part loading or part interchanging	02/06/2017	02/06/2017
47	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To improve weld quality (Blow Holes)	01/09/2013	01/09/2013
48	112303 - NAHARS ENGINEERING INDIA PVT. LTD	To prevent CO2 weld misplaced	07/06/2014	25/04/2013
49	107159 - NEEL AUTO PRIVATE LIMITED-Chakan	To prevent Cup rejection due to horse shoe Assembly	10/03/2013	12/03/2013
50	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of boring undersize / oversize.	20/09/2017	03/07/2017
51	108214 - BADVE ENGINEERING LIMITED-Pantnagar	To Prevent Customer Complaint of Boss welding given away in Brake Lever Pulsar K1	08/07/2017	25/05/2016
52	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of break padel bkt bush position tilt in D105 frame	20/07/2015	17/01/2015
53	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of dent marks on head pipe at number punching area in boxer's	20/07/2015	25/02/2015
54	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of grab.mtg bkt part position tilt in boxer's frame.	20/07/2015	10/01/2015
55	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of part missing (Head pipe stopper) in CT100 frame.	04/08/2015	18/07/2015
56	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of part missing in CT100 frame.	20/09/2017	20/09/2017
57	112933 - Metalman Auto Pvt Ltd.	To Prevent Customer complaint of seat cowl bkt shift in CT125 frame.	20/09/2017	20/09/2017
58	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaint of wrong side shocker bkt fitment in CT125 frame.	20/09/2017	15/08/2017
59	112933 - Metalman Auto Pvt Ltd.	To prevent customer complaints of spatters on eng.mtg bkt top in boxer's frame.	20/07/2015	20/07/2015
60	112303 - NAHARS ENGINEERING INDIA PVT. LTD	To prevent defect of cussing and pin hole	15/10/2013	19/10/2013
61	112933 - Metalman Auto Pvt Ltd.	To prevent defect of head pipe stopper bkt missing in D105 frame.	10/07/2015	22/04/2015

62	112933 - Metalman Auto Pvt Ltd.	To prevent defect of head pipe stopper position wrong fitment in boxer's frame.	19/07/2015	12/01/2015
63	112933 - Metalman Auto Pvt Ltd.	To prevent defect of horn mtg & cable hook bkt joint welding shift in Boxer's frame.	19/07/2015	17/05/2015
64	112303 - NAHARS ENGINEERING INDIA PVT. LTD	To prevent defect of wrong part fitment	19/08/2013	28/08/2014
65	112933 - Metalman Auto Pvt Ltd.	To prevent defect part position tilt of rear fendor bkt in D105 frame.	19/07/2015	15/02/2015
66	100189 - BADVE ENGINEERING LIMITED	TO PREVENT DENT & DAMAGE ON MUFFLER DURING PACKING	01/09/2012	15/09/2012
67	100189 - BADVE ENGINEERING LIMITED	To prevent dent & damages of Pipe A assly at spacer round welding stage	01/05/2014	06/05/2014
68	100189 - BADVE ENGINEERING LIMITED	To prevent Dent & damages on muffler at leakage testing stage	03/05/2014	10/05/2014
69	112303 - NAHARS ENGINEERING INDIA PVT. LTD	To prevent difficulty in lock fitment	07/06/2014	08/06/2014
70	100189 - BADVE ENGINEERING LIMITED	To prevent EFR & Warranty due to noise phenomena. Model-Disco 125 silencer Assly	28/08/2012	29/08/2012
71	108302 - NEEL AUTO PRIVATE LIMITED-Pantnagar	To Prevent EFR of fuel tank Drain Pipe blockage.	12/02/2017	12/02/2017
72	108302 - NEEL AUTO PRIVATE LIMITED-Pantnagar	To prevent internal rework due to seam leakage	30/12/2015	30/12/2015
73	112933 - Metalman Auto Pvt Ltd.	To prevent part missing defect in boxer's frame.	10/07/2015	17/01/2015
74	107159 - NEEL AUTO PRIVATE LIMITED-Chakan	To prevent Petrol Tank rejection due to Cup assembly tilt.	10/02/2013	25/02/2013
75	100189 - BADVE ENGINEERING LIMITED	To prevent rejection(rework) of silencer due to blow hole,i.e 1000 silencer in a month	05/12/2011	12/12/2011
76	112933 - Metalman Auto Pvt Ltd.	To prevent shabby welding defect on lower pipe joint in CT100 frame (CC- III rd party inspection).	21/07/2015	30/05/2015
77	105139 - KESHARDEEP PRESSINGS	To prevent spatter on thread -chain adjuster	10/11/2016	10/11/2016
78	100264 - RUCHA ENGINEERING PVT LTD.	To Reduce Customer Complaints	15/11/2014	20/11/2014
79	105518 - INNOVENTIVE INDUSTRIES LIMITED	To reduce excessive spatter generated.	27/03/2015	20/03/2015
80	100046 - YESHSHREE PRESS COMPS P LTD	To Reduce Floor Spot Damage	02/07/2014	03/06/2014
81	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	TO reduce I.H.R. about weld miss in engine hanger tube.	05/11/2014	30/11/2014
82	108214 - BADVE ENGINEERING LIMITED-Pantnagar	To reduce IHR due to welding shift in Fairing assly HF.	24/09/2014	06/09/2014
83	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To reduce IHR of frame boring dia undersize	01/10/2013	04/10/2013
84	100428 - BADVE AUTOCOMPS PVT LTD	To Reduce IHR of plug welding shift	02/02/2015	04/02/2015
85	112236 - BADVE ENGINEERING LIMITED. (2 Wh Waluj)	To reduce In house PPM	20/12/2014	10/12/2014

86	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To reduce inhouse defect of Rider Step not qualifying to relation gauge	07/01/2013	19/04/2013
87	114086 - LUMAX AUTO TECHNOLOGIES LIMITED	To reduce inhouse rework -Split Pin Hole shift	01/08/2013	03/08/2013
88	112303 - NAHARS ENGINEERING INDIA PVT. LTD	To reduce inspection time	22/07/2013	29/07/2013
89	100005 - Shreeganes Press N Coat	To Reduce passivation rework and rejection	20/12/2014	13/05/2014
90	100189 - BADVE ENGINEERING LIMITED	To reduce receipt rejection through Tier II vendor improvement.	21/01/2014	25/02/2014
91	113172 - BADVE AUTOCOMPS PVT LTD	To reduce rejection due to mouthpiece Welding Run shift	29/10/2016	04/11/2016
92	100046 - YESHSHREE PRESS COMPS P LTD	To Reduce Spatter Goes on Seat Mounting Stud	03/07/2014	05/06/2014
93	108214 - BADVE ENGINEERING LIMITED- Panthnagar	To reduce the IHR due to RR fender reinforcement bkt tilt weld.	24/09/2014	03/09/2014
94	100428 - BADVE AUTOCOMPS PVT LTD	To Reduce the IHR of Clutch cable hook missing.	26/02/2014	10/03/2014
95	100428 - BADVE AUTOCOMPS PVT LTD	To Reduce the IHR of K2 frame Side gusset bkt weld run shift.	14/10/2014	16/10/2014
96	113172 - BADVE AUTOCOMPS PVT LTD	To reduce the rejection of Connecting tube due to Flaring length variation (B 104D)	01/12/2016	09/12/2016