| | T | I | | | | | | | | | | | | | |
|---|-------------------------|--------------------|--|---|---------|---------------------|----------|----------------|--|--------|------|------|-------------------|-----------------|--|
| × | Equipment : | WELDING FIXTURE | | | | Loss Type : Quality | | | | | | | KAIZEN IDEA SHEET | | |
| | Department : | DM | | R | esult : | N | | P Q C D S M | | | | | | | |
| | Cell : | KITE -5 | | T | ype : | | | | | | | | К | nizen ID : 3028 | |
| Unit Name : Ruch | a Engineers Pvt Ltd I | Plant 2, Ahmedabad | | | Opera | tion : | | | | | | | | | |
| Kaizen Theme: TO I | MPROVE QUALITY | | Idea: Provide pin as per profile and restrict to mis-feed the part | | | | | | | | | | | | |
| Problem / Present Status | 3 | | Counter Measure | | | | | | Benchmark : | | | | | | |
| Earlier there was no provision to locate pipe profile to avoid miss-feed. | | | | | | | | Target : | | | | | | | |
| | | | | | | | | Start : | | 01/05/ | 2017 | | Finished : | 02/05/2017 | |
| | | | | | | | | Note : | | | | | | | |
| | | | | | | | | Team Members : | | | | | | | |
| | | | | | | | | 1. | | | | | 2. | | |
| | 2 line | - Landson | | | | | | 3. | | | | | 4. | | |
| | | A. C. | | | | | 5. | | | | | 6. | | | |
| | | | | | | | Benefits | | | | | | | | |
| | 77 | | | | | | | | | | | | | | |
| 12.5 | | The same of | | | | | | | | | | | | | |
| | 7 | | | | | | | | | | | | | | |
| Why Why Analysis : | | | Result: | | | | | | Kaizen Sustenance : | | | | | | |
| W1 : Part was getting freq | uently rejected | | | | | | | What T | o Do : | | | | | | |
| A1 : no profile locking | | | | | | | | | | | | | | | |
| W2 : Why no profile locking ? | | | | | | | | How To | How To Do: | | | | | | |
| A2 : not consider this defect in design stage | | | | | | | | | | | | | | | |
| W3: Why not consider this | s defect in design stag | ge? | | | | | | | | | | | | | |
| A3 : Now it is providing | | | | | | | | Freque | Frequency: | | | | | | |
| W4 : Why Now it is providi | ng ? | | | | | | | Cost Ir | Cost Incurred For Making Kaizen : | | | | | | |
| A4 : | | | | | | | | ı | Material | Cost | | Labo | ur Cost | Total | |
| | | | | | | | | | | | | | | 0 | |
| | | | | | | | | Scope | Scope & Plan For Horizontal Deployment : | | | | | | |
| Root Cause | | | - | | | | | | Equipmnet Target Stat | | | | | ıs | |
| Now it is providing | | | | | | | | | | | | | • | • | |
| Date : 02/05 | 5/2017 | | [] | | | | | | | | | | | | |
| Registered By: Ruch | a Engineers Pvt Ltd F | Plant 2 |] | | | | | | | | | | | | |
| Manager's Sign : | | | | | | | | | | | | | | | |
| Rucha Group - | Corporate | · - | | | | | | | | | | | | | |