×	Equipment :	6RU 809 391/392 Compo	Loss Type	Loss Type : Quality KAI7FN I								N IDEA SHEET			
	Department :	Tool Maintenance		Result :	N	_	P Q	Q C		S	М	TO CLE			
	Cell:	Production		Type :	+ '`	H	·	Ŭ	D		- ""	Ka	nizen ID : 3199		
Unit Name : Ruch	a Engineers Pvt Ltd I	Plant 7, Aurangabad	 , Aurangabad					tool							
Kaizen Theme: 6RU	809 391/392 Compo	und tool piercing issue solved	.(Burr issue)	: Wire	cut the	lan	d over hole	area 8	k add ne	ew wire	cut piero	ing button.			
Problem / Present Status			Counter Measure					Benchmark :							
391/392 compound tool, piercing hole land over so burr issue is happen.			Add new wire cut piercing button.			Target :									
							Start : 25/10/201		2017		Finished :	27/10/2017			
						_	Note :		20/10/2			i iiioiica :	21710/2017		
	12 10	-					Team Members :								
1							1. N.S.Gadhave					2. N.M.Jadhav			
4	10 (10)						3. K.H.Dhande			4. R.B.Jagtap					
	10 10	. 1					5.					6.			
							Benefits								
		1				C No need to making new blanking punch for only due to piercing land over. Rs 10500.00									
-			- 6				Q 100% Piercing hole burr issue solved Percent 100.00								
Why Why Analysis :			Result :				Kaizen Sustenance :								
W1: Why 391/392 compound tool, piercing hole burr issue due to land over.?							What To	What To Do : Check point added in PM check sheet							
A1 : Due to 391/392 compound tool, piercing hole land over. W2 : Why Due to 391/392 compound tool, piercing hole land over. ?								How To Do : Point will be checked in PM							
A2 : After in monthly PM reshaping was done to blanking punch							How To								
W3: Why After in monthly PM reshaping was done to blanking punch?															
A3 : Due to piercing not in button form							Frequer	Frequency : 2 month							
W4 : Why Due to piercing not in button form							Cost Inc	curred	For Ma	king K	aizen :				
?   A4 :							М	aterial	Cost Labor			ur Cost	Total		
								1350.0	00		60	0.00	1950.00		
							Scope 8	Scope & Plan For Horizontal Deployment :							
Root Cause			-					Equipmnet Target Stat					Target Status		
Due to piercing not in butto	on form														
Date : 25/10	/2017														
	a Engineers Pvt Ltd I	Plant 7													
Manager's Sign: Mr. S															
Rucha Group -	Corporate	<del></del>													