| × | Equipment : | Welding machine | Loss | Type : | Quality | / | | | | | | | KAIZEN IDEA SHEET | | | | |
|---|-------------------------|-----------------|---|---------------------|---------|---|----------------|--|-----------------------------------|---|------------|------------|-------------------|---------------|---------------|--|--|
| | Department : | Quality | | Resu | lt: | Ν | P | Q | С | D | S | | М | | | | |
| | Cell : | Jack | | Туре | : | | | | | | | | | Kai | zen ID : 3202 | | |
| Unit Name : Rucha Engineers Pvt Ltd Plant 6, Aurangabad Operation : Provide proper arrangement for checking screw hole. | | | | | | | | | | | | | | | | | |
| Kaizen Theme: To re | duce customer complai | nt | Idea : Provide proper arrangement for checking screw hole. | | | | | | | | | | | | | | |
| Problem / Present Status | | | Counter Measure | | | | | | Benchmark : 1 | | | | | | | | |
| APE forging screw hole missing | | | : Provide pin at the process stage through which every jack will pass and the operation missing can be identified at the same place | | | | | Target : 0 | | | | 0 | | | | | |
| | | | are operation moonly our be domined at the same place | | | | | Start : 17/11/2017 | | F | Finished : | 10/11/2017 | | | | | |
| × | | | × | | | | Note : | lote : | | | | | | | | | |
| | | | | | | | Team Members : | | | | | | | | | | |
| | | | | | | | 1. C P Jagtap | | | | | 2 | 2. B R Kangare | | | | |
| | | | | | | | 3. T K Hanwate | | | | | 4 | 4. | | | | |
| | | | | | 5. | | | | | 6 | 6. | | | | | | |
| | | | | | | | | Benefits | | | | | | | | | |
| | | | | | | | | Q Quality improve and also reduced customer complaint Nos 0.00 | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |
| Why Why Analysis : | | Result : | | Kaizen Sustenance : | | | | | | | | | | | | | |
| W1 : Why screw hole missing ? | | | Quality improve. | | | | | What To Do : Provide proper arrangement for checking screw hole. | | | | | | | | | |
| A1 : 100% inspection method not available | | | | | | | | | | | | | | | | | |
| W2 : Why 100% inspection method not available ? | | | × | | | | | Llaur Ta Da - Davida davial air is ficture for short but to the | | | | | | | | | |
| A2 : No proper arrangement for checking screw hole. | | | | | | | | How To Do : Provide dowel pin in fixture for checking hole Dowel pin present point added in check sheet | | | | | | | | | |
| W3 : | | | | | | | | | | | | | | | | | |
| A3 : | | | | | | | | | Frequency : Daily | | | | | | | | |
| W4 : | | | | | | | | | Cost Incurred For Making Kaizen : | | | | | | | | |
| A4 : | | | | | | | | Material Cost | | | | | Labour (| Cost | Total | | |
| | | | | | | | | | 0.00 | | | | 0.00 |) | 0.00 | | |
| | | | | | | | | Scope & Plan For Horizontal Deployment : | | | | | | | | | |
| Root Cause | | | | | | | Equipmnet | | | | | | | Target Status | | | |
| No proper arrangement for checking screw hole. | | | | | | | | | | | | | | | | | |
| Date : 17/11 | | | | | | | | | | | | | | | | | |
| | a Engineers Pvt Ltd Pla | nt 6 | | | | | | | | | | | | | | | |
| Manager's Sign : Mr. S | | | | | | | | | | | | | | | | | |
| Rucha Group - | Corporate | | | | | | | | | | | | | | | | |