Equipment : CT 125 FRame asse	mblyShoker bkt welding stage	Loss Type : Defect loss								KAIZE	KAIZEN IDEA SHEET		
Department : Materials		Result :	N	F	Q	Q C		S	М				
Cell: CD QA at Metalman	Valuj	Type :					D			Kaizen ID : 3230			
Unit Name : Press and Fab - Quality, Pune					<u> </u>				1				
Kaizen Theme: To prevent customer complaint of wrong shocker by	kt fitment Idea	ı: Poka	yoke pro	ovis	ion to arr	est wror	ng fitmer	nt of Sh	ocker bkt	during welding	g		
Problem / Present Status	Counter Measure				Benchmark :								
Possibility oh LH shocker bkt being welded on RH side	Step pin locator provided to shocker bkt & reid switch provided to locator cylinder to confirm the step pin position.			Target :									
					Start : 10/08/2017			2017		Finished: 15/08/2017			
×	×				Note :					•			
					Team Members :								
					1.					2.			
							3.				4.		
					5.					6.			
					Benefi	Benefits							
Why Why Analysis : Result :					Kaizen Sustenance :								
W1:	zero rejection				What To Do : Pokayoke check sheet update								
A1 :													
W2:					How To Do : Daily pokayoke audit								
A2 :	×			The To Bo . Bully policy one dudin									
W3:													
A3 :					Freque	ncy : Da	ily						
W4 :					Freque Cost Ir			king Ka	aizen :				
					Cost Ir		For Mal	king Ka		r Cost	То	al	
W4 :					Cost Ir	curred	For Mal	king Ka		r Cost	To		
W4 :					Cost Ir	Aaterial	For Mal						
W4 : A4 :					Cost Ir	Aaterial	For Mak		Labou Deploym				
W4 :					Cost Ir	Aaterial	For Mak	izontal	Labou Deploym		C)	
W4 : A4 : Root Cause					Cost Ir	Aaterial	For Mak	izontal	Labou Deploym		C)	
W4 : A4 : Root Cause Date : 11/12/2017					Cost Ir	Aaterial	For Mak	izontal	Labou Deploym		C)	
W4 : A4 : Root Cause					Cost Ir	Aaterial	For Mak	izontal	Labou Deploym		C)	