BAJAJ Distinctly Ahead	Equipment :	COVER TUBE ROUND WELDING					Defect	Lo	ss					KAIZEN IDEA SHEET					
	Department :	PRODUCTION	F	Result: N			Q	С	D	S	М	1							
	Cell :	BODY MUFFLER		Type :									] r	Kaizen ID : 2279					
Unit Name : 100189 - BADVE ENGINEERING LIMITED, Operat										ROUND WELDING									
Kaizen Theme: TP PR	REVENT THE IN HOL	JSE REJECTION OF EXCH	AUST PIPE A	ASSLY	Idea :	Cover	tube I.I	D. h	olding by	providi	ng locat	or blo	ck						
Problem / Present Status			Counter Measure						Benchmark: 86 Q			86 QTY	QTY/MONTH						
Exhaust pipe A assembly rejection due to cover tube tilt			Old resting block replaced by new modified locating block						Target: 0			0							
							Start :		21/11/2013		1	Finished :	Finished: 28/11/2013						
				×						Note :									
		Cover tube							Team Members :										
·									1. UM MADNE					2. B K HANWATE					
									3. SP SHINDE			4. BINITA PANDA							
									5.					6.					
									Benefits										
									C Rejection cost saved Rs 11000.00										
140 AU A I :		8	<b>5</b> 1/						1,7 .										
				Result: IN HOUSE REJECTION REDUCED FROM 86 TO 0						Kaizen Sustenance : What To Do : Tool / Fixture P.M. plan									
?		What To bo . Tool / Fixture Figure																	
A1 : Pipe B assly not insert	ted in pipe A assly																		
W2 : Why Pipe B assly not inserted in pipe A assly											How To Do : Point added in Tool / Fixture P. M. check sheet								
?																			
A2 : Pipe A assly cover tube tilt during round welding process				100 90 - 80 - 25 70 - 62 07 60 - 56						Frequency : DAILY & WEEKLY									
W3 : Why Pipe A assly cover tube tilt during round welding process										Cost Incurred For Making Kaizen :									
A3 : Cover tube holding with plain resting block				Ap 70 - 62 56 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1											_				
W4 : Why Cover tube holding with plain resting block ? A4 :			Se.					Material Cost		_	Labour Cost		T-	Total					
				, 0	0				540.00 225.00			765.00							
				Jan Ja	Lebry Boio	ction (	<b>3</b> 5.	Scope & Plan For Horizontal Deploym					/ment :	nent :					
Root Cause				• 1			■ Rejection Qty			Equipmnet					Target	Status			
Cover tube holding with plain resting block							ROUND WELDING					11/11/2013 COMPLETE							
Date : 21/11	/2013																		
	D Rathod																		
Manager's Sign: Mr. D																			
Bajaj Auto Ltd. (			-						-										