×	Equipment :	VERNIER CALIPER				Loss Type :	Qualit	ty						KAI	KAIZEN IDEA SHEET			
	Department :	QUALITY				Result :	N	Р	Q	С	D	s	М					
	Cell :	JACK ASSLY		Type :	De :							Kaizen ID : 3185						
Unit Name : Ruch	a Engineers Pvt Ltd Pla	ant 6, Aurangabad				Opera	ation :	Cr	Crimping									
Kaizen Theme: TO R	EDUCE CUSTOMER (COMPLAINT			Idea	: Provid	ded pin	on fi	xture fo	r locating	g screw	hole.						
Problem / Present Status	Counter Measure						Benchmark : 1											
Screw observed without hole at customer end			Provided pin on fixture for locating screw hole.						Target : 0									
		Start : 10/09/2017							Finished	Finished : 28/09/2017								
the second s		Note :																
		and a							Team	Member	's :							
AND PLAN							1. Mr. B R Kangre				2. Ms. T	2. Ms. T C Hanuwate						
						3. Mr. P U Patil				4. Mr. S	4. Mr. S K Mahajan							
		-							5.					6.	6.			
and the second second	Contraction of the local division of the loc	No. of Concession, Name							Benefits									
and the second									Q Reduce CC PPM PPM 0.00									
All Land									C Reduce COPQ Rs 750.00									
	<u> </u>						M Increase Moral Percent 100.00											
Why Why Analysis :	Result :						Kaizen Sustenance :											
W1 : Why Screw observed without hole at customer end ?			Reduce Customer complaints						What To Do : Point to be monitored.									
A1 : not arrest at final assl	-																	
W2 : Why not arrest at final assly area. ?			3 Result						How To Do : Point added in PM check list.									
A2 : No provision of hole location in fixture.																		
W3 : Why No provision of hole location in fixture. ?																		
A3 : Provided pin on fixture for locating screw hole.			2						Frequency : Weekly									
W4 : Provided pin on fixture for locating screw hole. A4 :									Cost Incurred For Making Kaizen :									
			1 1						Material Cost Lab			oour Cost	ur Cost Total					
										75.0	0			300.00		375.00		
			0	Before		After			Scope & Plan For Horizontal Deployment :									
Root Cause									Equipmnet					Target	S	Status		
Provided pin on fixture for locating screw hole.									Gantry fixture 0					05/11/2016	COM	IPLETE		
Data : data	20047																	
	0/2017 a Engineers Pvt Ltd Pla	ant 6																
IREGISTERED BV : RUCH	a Engineers PVt Ltd Pla	מונט	1															
Manager's Sign : Mr. S																	1	