×	Loss Type : Materi					ial I	loss					KAIZEN IDEA SHEET								
	Department :	Production				Result: N		Т	P Q C		D S		М			0				
	Cell:	CNC Machine Engine					Type :	11	╁	1 Q				IVI	1	Kaizen ID : 5	504			
Unit Name : Hero							·	peration :		Mirror plate	nackir					Naizeii ID . 334				
1 7 3												lirror plate packing								
Kaizen Theme: To re	Idea: Stand for wet glas																			
Problem / Present Status			Counter Measure							Benchn	Benchmark: 0									
Scratch rejection is high at final washing stage			A wooden stand provided for wet glass plate resting so that there is no contct between plates to avoid scratches						Target: 0			0								
			Section place to area solutions							Start : 02/08/2013				Finished	: 02/0	8/2013				
Control Control	100		1			2 0		1/10	7 /	Note:					•	<u> </u>				
										Team Members :										
The state of the s									1. Mr. Ram Yadav					2. Mr. Ravi Chopra						
									3. Mr. Nitish Gore					4. Mr. Sameer Joshi						
										5. Mr. Jay Kadam					6. Mr. Ajit Pawar					
											Benefits									
											Q Scratch rejection at final washing stage reduced Nos 20.00									
7																				
		11. 1. 16	7		188															
Why Why Analysis :			Result:							Kaizen Sustenance :										
W1 : Why Scratch rejection is high at final washing stage ?			Scratch rejection at final washing stage reduced							What To Do: To check perodically for effective working of unit										
A1 : Rubbing of wet glass plates with each other																				
W2 : Why Rubbing of wet glass plates with each other ?										How To Do : Cross check by operating by group leader										
A2 : No stand for wet glass plate resting			50 7 45																	
W3:			40	-		Scratch	n Rej. / shift													
A3:			30 98. 20 20							Frequer	Frequency : Twice in shift									
W4 :				o -						Cost Inc	Cost Incurred For Making Kaizen :									
A4 :										М	aterial (Cost		Labo	our Cost		Total			
			0		Before	1	0		_		500.0	0		1	00.00	6	600.00			
							After			Scope & Plan For Horizontal Deploy				al Deploy	ment :					
Root Cause No stand for wet glass plate resting												Equ	iipmne	et		Target	Status			
										MAZAK	MAZAK H.M.C. 630 N(200.5)					02/08/2013 COMPLETE				
Data : 00/00	12042																			
	s/2013 nima.menge@opexwo	irks com																		
Manager's Sign: Mr. A		IIIOUIII																		
Hero Moto Corp																				
11010 111010 001																				