



	Equipment :	Joining Front and Rear Body	Loss Type :	Defect Loss							KAIZEN IDEA SHEET Kaizen ID : 2399	
	Department :	production	Result :	N	P	Q	C	D	S	M		
	Cell :	mega body	Type :									
Unit Name : 100046 - YESHSHREE PRESS COMPS P LTD, Aurangabad			Operation : Joining Front and Rear Body									
Kaizen Theme: To Reduce Spatter Goes on Seat Mounting Stud			Idea : Providing Cover Seat Mounting Stud									
Problem / Present Status		Counter Measure			Benchmark :		100%					
					Target :		zero					
					Start :		05/06/2014		Finished :		05/06/2014	
					Note :							
					Team Members :							
					1. Mr.S.N.Tambekar		2. Mr.N.P.Sukashe					
3.		4.										
5.		6.										
Benefits												
Q		1) Eliminate CC Rs 0.00										
C		2) Reduced Rework Cost Rs 0.00										
Why Why Analysis :		Result :			Kaizen Sustenance :							
W1 : W 1) Spatter Goes on Seat Mounting Stud		Reduce spatter			What To Do : Add in Daily Quality Audit Check Sheet							
A1 : A 1) No Cover Available												
W2 : Why A 1) No Cover Available ?					How To Do : Daily as per Quality Audit Check Sheet							
A2 :												
W3 :												
A3 :												
W4 :												
A4 :												
Root Cause												
A 1) No Cover Available												
Date : 03/07/2014												
Registered By : Mr. Amol Dadpe												
Manager's Sign : Mr. S.R.Phatale												
----- Bajaj Auto Ltd. (Fabrication) -----												