

	Equipment :	Fixture	Loss Type :	Defect Loss							KAIZEN IDEA SHEET Kaizen ID : 2788
	Department :	QA	Result :	N	P	Q	C	D	S	M	
	Cell :	Fabrication	Type :								
Unit Name : 110865 - METALMAN MICRO TURNERS,			Operation :								
Kaizen Theme: To eliminate the Customer complaint Chain case bolt not fitting in chain case hole at Bal Pulsar lin			Idea :								
Problem / Present Status		Counter Measure			Benchmark :						
					Target :						
					Start : 09/03/2016		Finished : 10/03/2016				
					Note :						
					Team Members :						
					1.		2.				
					3.		4.				
					5.		6.				
					Benefits						
Why Why Analysis :		Result :			Kaizen Sustenance :						
W1 : A1 : W2 : A2 : W3 : A3 : W4 : A4 :					What To Do :						
					How To Do :						
					Frequency :						
					Cost Incurred For Making Kaizen :						
					Material Cost		Labour Cost		Total		
									0		
					Scope & Plan For Horizontal Deployment :						
Root Cause					Equipmnet		Target		Status		
Date : 09/03/2016											
Registered By : Mr. Ajit Singh											
Manager's Sign :											
----- Bajaj Auto Ltd. (Fabrication) -----											