

	Equipment :	Rear Box 3 rd assly.	Loss Type :	Defect Loss							KAIZEN IDEA SHEET Kaizen ID : 2899
	Department :	QA	Result :	N	P	Q	C	D	S	M	
	Cell :	CT100 A	Type :								
Unit Name : 112933 - Metalman Auto Pvt Ltd., Aurangabad			Operation :								
Kaizen Theme: To prevent customer complaint of spatters on shock abs. stud in CT100			Idea :								
Problem / Present Status		Counter Measure			Benchmark :						
					Target :						
					Start : 14/04/2016		Finished : 16/04/2016				
					Note :						
					Team Members :						
					1.		2.				
					3.		4.				
					5.		6.				
					Benefits						
Why Why Analysis :		Result :			Kaizen Sustenance :						
W1 :					What To Do :						
A1 :											
W2 :					How To Do :						
A2 :											
W3 :					Frequency :						
A3 :					Cost Incurred For Making Kaizen :						
W4 :					Material Cost			Labour Cost		Total	
A4 :										0	
Root Cause					Scope & Plan For Horizontal Deployment :						
Date : 22/09/2016					Equipmnet		Target	Status			
Registered By : Mr. D S Lade											
Manager's Sign :											
----- Bajaj Auto Ltd. (Fabrication) -----											