

	Equipment :	Forward Assly.	Loss Type :	Defect Loss							KAIZEN IDEA SHEET Kaizen ID : 2900
	Department :	QA	Result :	N	P	Q	C	D	S	M	
	Cell :	CT100 A	Type :								
Unit Name : 112933 - Metalman Auto Pvt Ltd., Aurangabad			Operation :								
Kaizen Theme: To prevent customer complaint of spatters at head pipe number punching area in CT100 frame.			Idea :								
Problem / Present Status		Counter Measure			Benchmark :						
					Target :						
					Start :		19/04/2016		Finished :		22/04/2016
					Note :						
					Team Members :						
					1.			2.			
					3.			4.			
					5.			6.			
					Benefits						
Why Why Analysis :		Result :			Kaizen Sustenance :						
W1 :					What To Do :						
A1 :											
W2 :					How To Do :						
A2 :											
W3 :					Frequency :						
A3 :					Cost Incurred For Making Kaizen :						
W4 :					Material Cost		Labour Cost		Total		
A4 :									0		
Scope & Plan For Horizontal Deployment :											
Root Cause					Equipmnet		Target		Status		
Date : 22/09/2016											
Registered By : Mr. D S Lade											
Manager's Sign :											
----- Bajaj Auto Ltd. (Fabrication) -----											