-	Equipment :	Silencer leak test M/C.	Loss Type: DIE / JIG /										W A 17F	NIDEAC	UEET		
	Department :	Press and Fab - Quality											KAIZEN IDEA SHEET				
	-	•	MMT Part ross	Result			Р	Q	С	D	S	М					
	Cell:	Platina Silencer leak test -	MM1, Pant nagar	Type :						<u>. </u>			Ka	Kaizen ID : 3251			
Unit Name : Press	and Fab - Quality, Pเ	une			Operatio	on :	Pla	tina siler	ncer lea	akage te	esting						
Kaizen Theme: To red	luce silencer leak tes	t m/c spare cost.	lde	a :	To provid	de m	etalic	block wi	ith sma	ll teflon	resting	pads.					
Problem / Present Status			Counter Measure					Benchmark: Rs				Rs 5000	s 5000/month				
At present we use Teflon block as resting pad for silencer during leak testing process. So frequently wear & tear of teflon blocks. So high spare cost			Teflon block is replaced with metalic block. Small teflon pads provided at contact point of silencer with metalic block.					Target: Rs				Rs 350 /	s 350 /month				
process. So frequently wea	a teal of tellori bloc	ks. 30 flight spare cost	Softage point of silencer with metallo block.					Start : 02/01/2018			•	Finished: 05/01/2018					
×			×				— [ī	Note :					•				
									Team Members :								
								1. Mr. Pradeep s Patil					2. Mr. Kamal Kant				
								3. Mr. Kamalsingh Tomar				4.					
								5.					6.				
									;				•				
Why Why Analysis :			Result:					Kaizen Sustenance :									
W1 : Why High spare cost. ?			Teflon block cost reduced from Rs 5000/month to Rs 350/month.					What To Do : Check Wear of teflon rest pads.									
A1 : Continious resting bloc																	
W2 : Why Continious resting block replacement ?								How To Do: Through JH check sheet.									
A2 : Heavy wear & tear of blocks			×														
W3 : Why Heavy wear & tea	ar of blocks?						L										
A3 : Teflon blocks used.								Frequen	cy : Da	ily							
W4 : Why Teflon blocks used. ?							Ī	Cost Inc	urred	For Ma	king K	aizen :					
A4 :								Material Cost Labour Cost				To	Total				
							Ī		0.00			0	00	0.0	00		
								Scope & Plan For Horizontal Deployment :									
Poet Cause							ı		Equipmnet Target St					Status			
Root Cause Teflon blocks used.							-	· ·									
Date : 10/01/	2018																
			1														
Registered By: Mr Pra	adeepkumar Patil																
Registered By: Mr Pra Manager's Sign: BAL Prass and F																	